

NOT COURT YED		SF	TENS	UNITS	MONTH	DAY	NITE	COM- BAT MIS- SION	DAMAGE	INJURY	FATAL	SER.	MINOR	HIDE	VI	V	IV	III	II	I	PARA- CHUTE						
			0	7	4	10	7	4	1	2	7	U	2														
			LOCATION			DATE			PURPOSE			SPECIAL NO.															
			15 February 1951			2150			At sea, 1 mi W of Pt Loma, San Diego, Calif			Nite Special Exercise			1-51												
			PILOT'S NAME, RANK, & SERVICE GROUP & UNIT TO WHICH PILOT ATTACHED																								
			HESSOM, ROBERT CHARLES, LTJG USN VC-35																								
			UNIT TO WHICH AIRCRAFT ASSIGNED OPERATING FROM CHAIN OF COMMAND																								
			VC-35, NAS, SAN DIEGO, CALIF, COMAIRPAC																								
			PILOT'S INSTRUMENT RATING		TOTAL HOURS THIS MODEL		TOTAL HRS. LAST 3 MONTHS		HRS. THIS MODEL LAST 3 MONTHS		TIME IN FLIGHT		WEATHER AT TIME OF ACCIDENT							INSTRUMENT HRS. LAST 6 MONTHS		INSTRUMENT HRS. LAST 3 MONTHS		TYPE OF CLEARANCE			
			ST		2055		86.5		107		86.5		1.7		<input checked="" type="checkbox"/> CONTACT <input type="checkbox"/> INSTRUMENT											VER	
			PREVIOUS ACCIDENT RECORD																								
			7-22-46 8-1-46 3-1-47																								
			INJURIES TO PILOT																								
			None D																								
			NAME & RANK OF OTHER PERSONNEL																								
			INJ.																								
			B Collision Water Forced Landing																								
			AIRCRAFT MODEL & NO.																								
			AD1Q #09378																								
			INSTRUMENT RATING OF AIRCRAFT																								
			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																								
			DID FIRE FOLLOW IMPACT																								
			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																								
			WAS PARACHUTE USED																								
			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																								
			DAMAGE A B C D E																								
			Strike																								
			AIRCRAFT X																								
			ENGINES																								
			GEN. NATURE																								
			E-18																								
			SPECIFIC TYPE ACCID.																								
			4																								
			Forced landing - loss power fuel exhaustion																								
			CAUSE ANALYSIS																								
			PP-9 Power failure, undetermined failure of fuel system suspected.																								
			CLASSIFICATION OF ACCIDENT CAUSES																								
			MAT PP (fuel system)																								
			GENERAL NATURE OF ACCIDENT — PRIMARY-BOTTOM ROW																								
			SECONDARY-TOP ROW																								
			SPECIFIC TYPE OF ACCIDENT — PRIMARY-BOTTOM ROW																								
			SECONDARY-TOP ROW																								
			AIRCRAFT ACCIDENT CARD FORM NAVAER 339 C (REV. 9-45)																								
			D R A-B O																								
			X X																								

ACCIDENT - Hessom took off from NAS North Island accompanied by wingman Ens. Lawrence. The 2 a/c rendezvoused at 2030 with 7 LST's located at 31-40N 117-52W which bears 209T, 65 miles from North Island, & proceeded to carry out the scheduled & pre-arranged simulated attacks on the surface craft. The highest power settings used by Hessom after takeoff were 35" MP and 2400 rpm.

Nothing unusual occurred until Hessom noted that on subsequent observations of his fuel quantity gage the amt indicated fluctuated from 1600 lbs to well past the full position. He assumed his indicator was inoperative, reported this fact to his wingman & asked for a fuel check. His wingman had 1500 lbs of fuel remaining. Hessom made one more attack & then noted that his gage indicated 550 lbs. At this time he decided to terminate the exercise & return to base. He had no indication of fuel fumes in the cockpit at any time. On the return flight to North Island he endeavored to conserve fuel. The fuel quantity indicator showed a rapid consumption of fuel up to the time of engine failure. Engine failure occurred approx 4 miles W of Pt Loma. He notified his wingman & emergency radio transmissions were made on Navy tower channel 2, frequency 142.74 mc. Hessom continued to head for land until he reached 1660'. At this point he turned to NWly heading to take advantage of moonlight. The ditching was made with wheels up, flaps down & canopy open. He unbuckled his parachute but left straps over his shoulders & tightened his shoulder straps prior

to impact. 2 impacts were felt & a/c swerved to right. Neither impact was very severe & no injuries resulted.

When Hessom made his exit from a/c the chute slipped off his shoulders. After he had left the cockpit he endeavored to pull chute out of the a/c but his efforts were unsuccessful. Hessom used his 2 MK13 flares & tracer bullets from his .38 cal. revolver & standard 2 cell flashlite to signal rescue craft. Hessom was picked up by Coast Guard crash boat at 2213.

CONCLUSIONS & REC - It is concluded that engine failed because of fuel exhaustion. The exhaustion of fuel, on flight of 1/3rd the a/c's expected endurance, is believed due to an unknown material failure. The possibility exists that damage rec'd in previous x-dent could have brought about the failure of engine in flight but no evidence could be obtained to substantiate this.

No recommendations for the prevention of similar x-dent can be made due to lack of evidence on nature of the failure.

It is recommended that all pilots be briefed on the importance of retaining all their survival gear regardless of the proximity of rescue facilities. Emphasis should be placed on making exit from a/c with para-raft, which is approx 30% of the weight of the chute & raft combined, & then if time permits retrieve the chute.

CO - In view of: (1) statement by pilot, plane capt & gassing detail, 2) the gas log entry of 253 gals of gas having been put in a/c on 2nd fueling & 3) the relatively short duration of the flight, the opinion of the x-dent bd, altho not very helpful from future accident prevention standpoint, is concurred in. It is felt that Hessom noticed that he was having fuel trouble as quickly as he could reasonably be expected to - perhaps even more quickly than would normally be case. However, this x-dent definitely emphasizes the vital necessity of constantly checking all instruments which provide info affecting safety of flt & importance of indoctrinating pilots so that it is procedure becomes an integral part of their flying technique.

The Squad Survival Officer has been directed to concentrate on ditching drills, emphasizing the abandonment of the cockpit both with chute & para-raft, & with para-raft only.